Premier Inspections



January 9th 2021, 12:49 pm

Inspection performed by:

J Longley

4058088269

j@premierinspectionsok.com

General Information

BUILDING ADDRESS: CITY: STATE: **ZIP CODE: INSPECTION DESCRIPTION:** SQUARE FOOTAGE:

2422 N Park Dr Stillwater OK 74075 Hernandez house 1247

Picture:



Has the PRE-INSPECTION AGREEMENT been signed by the client? Yes

Is the client present for the inspection?

Only for part of the Inspection

Is the real estate agent present for the inspection?

No

EXTERNAL AMENITIES

GATE Satisfactory Notes:



FENCE Satisfactory Notes: ROOF ROOF TYPE Gable Notes:



ROOF MATERIAL Asp

Asphalt Shingles

Notes: SHINGLES MISSING / DAMAGED? Satisfactory Notes: ROOF INSTALLATION Fair Notes:

















Fair

SKYLIGHTS / ROOF PENETRATIONS Notes: MILDEW PRESENT ON ROOF? No Notes: EXTERIOR SIDING MATERIAL Other Notes: combination brick and wood SIDING CONDITION Fair

Notes:



FLASHING Satisfactory

Notes: **EAVES** Satisfactory Notes: **FASCIA** Satisfactory Notes: **SOFFITS** Fair Notes:







EXTERIOR DOORS Satisfactory Notes: STOOP / PORCH Satisfactory Notes:





PATIO Fair Notes:



LANDSCAPE

VEGETATION Satisfactory Notes: GRADING Satisfactory Notes: SURFACE DRAINAGE Satisfactory

Premier Inspections Confidential - for client use only. Use by any unauthorized persons is prohibited

Notes: WALKWAYS Satisfactory Notes:

GARAGE

DRIVEWAY Satisfactory Notes:

GARAGE DOOR Satisfactory Notes: GARAGE DOOR OPENER Satisfactory Notes: EXTERIOR DOORS Satisfactory Notes:

ATTIC

ROOF SHEATHING Satisfactory Notes: FRAMEWORK Satisfactory

Notes:



VENTILATIONSatisfactoryNotes:SatisfactoryNotes:Satisfactory



ACCESS Fair Notes: MILDEW PRESENT IN ATTIC? No Notes: SIGNS OF PESTS IN ATTIC? No

Premier Inspections Confidential - for client use only. Use by any unauthorized persons is prohibited





FLOORING Satisfactory
Notes:
WALLS Satisfactory
Notes:
WINDOWS Satisfactory
Notes:
CEILING Satisfactory
Notes:
COUNTERS Satisfactory
Notes:
SINKS Fair
Notoo

Notes:

stopper does not completely block drainage but water temperature and drainage is satisfactory



BATHTUB / SHOWERSatisfactoryNotes:SatisfactoryNotes:SatisfactoryOUTLETSSatisfactoryNotes:Satisfactory



LIGHTING Satisfactory Notes: VENTING Fair

Notes:

Built-in fan very noisy with metal-on-metal sound along with slight burning smell. Recommend further evaluation by a HVAC technician





BATHROOM 2 DOORS Satisfactory Notes:



FLOORING Satisfactory Notes: WALLS Satisfactory Notes: **CEILING** Satisfactory Notes: **COUNTERS** Satisfactory Notes: **SINKS** Fair Notes:





BATHTUB / SHOWER Satisfactory

Notes:

TOILET Satisfactory

Notes:

OUTLETS Poor

Notes:

Open ground on bathroom outlet. This is an electrical safety hazard. Recommend further evaluation and correction by a licensed electrician



LIGHTING Satisfactory Notes: VENTING Satisfactory Notes: BEDROOM 1 DOORS Satisfactory

Notes:



FLOORING	Satisfactory
Notes:	
WALLS S	atisfactory
Notes:	
WINDOWS	Satisfactory
Notes:	
CEILINGS	Satisfactory
Notes:	
CLOSETS	Satisfactory
Notes:	
OUTLETS	Satisfactory
Notes:	



LIGHTING Satisfactory Notes: CEILING FANS Satisfactory Notes:

BEDROOM 2

DOORS Satisfactory Notes:



FLOORING Satisfactory

Notes:	
WALLS S	atisfactory
Notes:	
WINDOWS	Satisfactory
Notes:	
CEILINGS	Satisfactory
Notes:	
CLOSETS	Satisfactory
Notes:	
OUTLETS	Satisfactory
Notes:	
LIGHTING	Satisfactory
Notes:	
CEILING FA	NS Satisfactory
Notes:	

BEDROOM 3

DOORS Satisfactory Notes:



FLOORING Satisfactory Notes: WALLS Satisfactory

Notes:	
WINDOWS	Satisfactory
Notes:	
CEILINGS	Satisfactory
Notes:	
CLOSETS	Satisfactory
Notes:	
OUTLETS	Satisfactory
Notes:	




LIGHTING Satisfactory Notes: CEILING FANS Satisfactory Notes: LIVING AREA 1 DOORS Satisfactory Notes:



FLOORINGSatisfactoryNotes:WALLSWALLSSatisfactoryNotes:SatisfactoryNotes:SatisfactoryNotes:Satisfactory





Notes: LIGHTING Satisfactory Notes: CEILING FANS Satisfactory Notes: KITCHEN DOORS Fair Notes:



FLOORING Satisfactory
Notes:
WALLS Satisfactory
Notes:
WINDOWS Satisfactory
Notes:
CEILING Satisfactory
Notes:
COUNTERTOPS Satisfactory
Notes:
CABINETS Satisfactory
Notes:
SINK / GARBAGE DISPOSAL Satisfactory
Notes:
DISHWASHER Satisfactory

Notes:



STOVE / OVEN Satisfactory Notes:



EXHAUST HOOD Notes:

Satisfactory



REFRIGERATOR Satisfactory Notes:



OUTLETS Poor Notes:



FOUNDATION FOUNDATION MATERIAL **Brick** Notes: SLAB Satisfactory Notes: Satisfactory WALLS Notes: FRAMEWORK Satisfactory Notes: DRAINAGE Satisfactory Notes: VENTILATION Satisfactory Notes: OUTLETS Satisfactory Notes: **MILDEW PRESENT AT FOUNDATION?** No Notes: **PLUMBING** WATER HEATER N/A

Notes:



ELECTRICAL

SERVICE DROP / LATERAL Satisfactory Notes: CONDUCTORS Satisfactory Notes: OVERCURRENT PROTECTION Poor Notes: RECEPTACLES Poor Notes: AMP RATING 100 Amps Notes:



MAIN DISCONNECTSatisfactoryNotes:WIRING METHODNon-Metallic Sheathed Cable

Notes: CIRCUIT PANEL Poor Notes:




HEATING SYSTEM Forced Air Notes: ENERGY SOURCE Natural Gas Notes: HEATING & COOLING HEATING SYSTEM OPERATION Satisfactory

Notes:



DUCTWORK / PIPING

Satisfactory





COOLING SYSTEM OPERATION Notes:

THERMOSTAT Satisfactory

Notes:



AIR FILTER(S) Satisfactory

Notes:

SMOKE ALARM(S) Poor

Notes:

Recommend smoke alarms be installed in all bedrooms and living areas. Currently only one installed in kitchen. It is functioning as intended

Satisfactory

CARBON MONOXIDE ALARM(S) Satisfactory

Notes: ADDITIONAL DETAILS

SUMMARY: